

IWAI/KOL/MM/14/Repair Gen

24.07.2015

CORRIGENDUM FOR REPAIR OF IWAI JOLLY BOAT IN KOLKATA/HOWRAH.

NIQ published in IWAI website on 16.7.2015 for Repair of IWAI jolly boat in Kolkata/Howrah , Serial no.02 in given BOQ the quantity shall be 5 cft instead of 50 cft. The fresh BOQ is attached. Last date of submission of quotation is extended upto 28.7.2015 upto 1400 hrs. Date of opening of submitted quotations: 28.7.2015 at 1500 Hrs. The other terms & conditions remains the same.

DIRECTOR

CORRIGENDUM

BOQ FOR REPAIR OF JOLLY BOAT OF IWAI AT BISN KOLKATA/ BOTANICAL GARDEN JETTY HOWRAH.					
Sl no.	Description	Unit	Qty	Rate	Amount
1	Cropping and renewal of steel plates with existing thickness MS plates in hull, ship side of the jolly boat and construction of a tarpaulin rig on the aft side of the boat as required as per direction of EIC.	kgs	600		
2	Cropping and renewal of salwood with existing thickness for seating arrangement in the jolly boat as required as per direction of EIC.	cft	5		
3	Overhauling of engine (make Kirloskar, 2 cylinder) along with gear box and stern gear units i.e. propeller, shaft, rudder after renewal of spare parts as required along with machining, re-metalling, head testing, calibration of pump & injectors etc, as required to make it operational as per direction of EIC.				
a	Labour charges	no.	1		
b	Cost of spares (actual +10%)				
4	Full boat to be painted with one coat of red oxide primer followed by two coats of green/blue as required after proper chipping, wire brushing and cleaning as per direction of EIC.	sq.m	50		
	Total				