



भारतीय अन्तर्देशीय जलमार्ग प्राधिकरण

(पोत परिवहन मंत्रालय, भारत सरकार)

INLAND WATERWAYS AUTHORITY OF INDIA

(MINISTRY OF PORTS, SHIPPING & WATERWAYS, GOVT. OF INDIA)

P-78, GARDEN REACH ROAD, KOLKATA - 700 043

पी०-७८, गार्डरीच रोड, कोलकाता-७०००४३

GRAM - JALMARG, Phone :- 2439 - 0393 / 1710 / 6055 / 5577 Telefax :- 2439 - 5570, E-mail:- iwaical@yahoo.com

IWAI/KOL/MM/23/2021-2022/Guwahati Vessels/

19.07.2022

Notice Inviting Quotation

Sealed quotations are invited from reputed and experienced ship repairer/builder for HRP repair works of HSD Jiaborali at Howrah, West Bengal as per the annexure enclosed herewith on the following term and conditions.

TERMS & CONDITIONS

- 1.) The price may be quoted including all the costs such as labor, materials and transportation etc. as per annexure. No other extra charges will be entertained. GST shall be reimbursed on submission of remittance.
- 2.) The work/repair shall be completed at Shibpur, Ch.141 within 5 (Five) days from the date of the work order, as per direction of EIC.
- 3.) The firm should also require submitting self-certified copy of PAN Card, GST registration certificate and work experience certificate etc.
- 4.) Payment will be made by RTGS within fifteen days from date of receipt of the bill along with receipt challan and duly certification of the bill by the officer concerned after deducting the statutory dues if any.
- 5.) The work shall be under guaranteed period of six months from the date of completion.
- 6.) In case of delay in completion of work, liquidated damage @ 0.5% per week subject to a maximum of 5% will be charged.

The sealed quotation should reach to IWAI, Kolkata Office latest by 20.07.2022 at 1500 hrs. The sealed bids will be opened on 20.07.2022 at 1530 hrs.

Encl.: As stated.

DIRECTOR

Head Office :- A-13, Sector- I, NOIDA, U.P. Pin - 201301.

Ph:- 0120-2543972/4004/4036/2521764. Fax: - 0120-2543973/4009/4041/2521664,

Email:- iwainoi@hub.nic.in Web site :- www.iwai.nic.in

Annexure - BOQ

S. N o	Description of Works	Unit	Qty .	Rate (Rs.)	Amount (Rs.)
1.	Front and Stbd side HRP unit propeller has rotation and command issues the same has to rectified/repaired to make operational in all respect including indicator etc. as required per direction of EIC.	No.	2		
a)	Total Labour cost				
b)	Cost of spares (actual+10%)				
	GRAND TOTAL(Excluding GST)				
	In Words _____ _____ (Excluding GST)				