



Phone : 0361-2676925, 2676929, 2570099  
Email : [dirguw.iwai@nic.in](mailto:dirguw.iwai@nic.in)  
Website : [www.iwai.nic.in](http://www.iwai.nic.in)



सत्यमेव जयते

भारत सरकार  
GOVT. OF INDIA

पत्तन, पोत परिवहन और जलमार्ग मंत्रालय  
Ministry of Ports, Shipping & Waterways

भारतीय अन्तर्देशीय जलमार्ग प्राधिकरण  
INLAND WATERWAYS AUTHORITY OF INDIA

Pandu Port Complex, Pandu, Guwahati-781 012, Assam

No. IWAI/GHY/Anchor Pontoon/4(77)/2022-23/1218

16<sup>th</sup> December 2023

### NOTICE INVITING QUOTATION

Sealed quotations are invited from the reputed Contractor/repairer/authorized dealer for annual afloat repair of **Anchor Pontoon – VI** at NW-2 as per annexure & as per terms and conditions laid down below. The NIQ can also be downloaded from IWAI's website ([www.iwai.nic.in](http://www.iwai.nic.in)).

- (2) The repair work may be done as per following terms and conditions mentioned below: -
- (i) The price may be quoted in both words and figures.
  - (ii) The price may be quoted including all the cost such as labour, transportation charges, all taxes excluding Good & Service Tax (GST) as applicable which will be paid on production of proof of payment. **No other charges shall be entertained.**
  - (iii) The repair work must be completed within 15 days from the date of receipt of order at Guwahati.
  - (iv) The firm has to submit documentary evidence of current copy of the Registration Certificate, PAN and GST.
  - (v) The payment shall be made by RTGS/ PFMS within 15 days from the date of receipt of bill and challan after satisfactorily work done. The copy of RTGS details shall be submitted along with quotation.
  - (vi) In Case of delay in completion of work liquidity damage @0.5% per week subject to a maximum of 5% will be charged.
  - (vii) The firm shall be having experience working with IWAI / IWT Wing / Port, etc. Supporting documents has to be attach.
  - (viii) IWAI reserves the right to accept or cancel any / all quotations without assigning any reason or any prior notice.
- (3) The sealed quotation should reach this office latest by **20.12.2023** at **15:00 hrs** and will open on same day at **15.30 hrs**. No quotation will be accepted after the last date and time for submission of quotations.

Encl: as stated above.

Copy to:-

- i) Accounts Section, IWAI, Guwahati
- ii) Office Notice Board,

  
16/12/2023  
DIRECTOR

Head Office :- I.W.A.I., A-13, Sector-1, NOIDA - 201 301 (U.P.)

• E-mail : [iwainoi@nic.in](mailto:iwainoi@nic.in) • Phone No :- 0120-2543972, 2543973, 2544004, 2521664, 2544036, 2522971.

**BOQ FOR ANNUAL AFLOAT REPAIR OF ANCHOR PONTOON - VI FOR THE YEAR 2023-24.**

SI No	Description of work	Unit	Qty	Estimated	
				Rate (in ₹)	Amount (in ₹)
1	Servicing of engine, make-Kirloskar, 10 HP; to be carried out. It is reported that, block of engine is cracked, the same has to renewed, making fully operational in full load, as required as per direction of EIC.	Comp. Job	1		
2	The alternator Make: Kirloskar, 7.5 KVA has to be serviced with exciter & AVR check, heat varnishing, megger testing and insulation checking as required as per direction of EIC.	Comp. Job	1		
3	Supply and fitting of reputed make gasket/packing to make leak/weather proof in all manhole (No.5); nut bolts replace with SS as required as per direction of EIC.	Comp. Job	1		
4	Supplying and fitting of SUV tyre fender on both side of deck as required as per direction of EIC.	No.	8		
5	Supply and fitting of reputed make cover for anchor winch, control panels and alternator as required as per direction of EIC.	Comp. Job	1		
6	Entire line and wiring of both panel boards including MCB, indicator light and switches are to be checked and rectified as required as per direction of EIC.	Comp. Job	1		
7	Winch gearbox to be serviced/repaired as required as per direction of EIC.	Comp. Job	1		
8	Winding, checking, varnishing and fitting of winch motor as required as per direction of EIC.	Comp. Job	1		
9	Panel board of genset was damaged and unable to lock the same has to be rectified and paint has to made in & out as required as per direction of EIC.	Comp. Job	1		
10	Servicing of winch system including motor and gearbox & replacement of wire rope, as required as per direction of EIC.	Comp. Job	1		
11	The entire ship side shell plate from LWL to deck plate, superstructure, pulley-winch structure, vent pipe, in side of manhole (No.5) along with other fitment etc., are to be proper cleaned, scrapped, wire brushed, chipped and painted (1 coat prime & 2 coat marine paint) as required as per direction of EIC/ Surveyor.	Comp. Job	1		
TOTAL (exclu.GST)					

In Words:



Handwritten signature and initials, possibly reading '16/12/23' and 'DR'.