

No. IWAI/GHY/HPTBRAmbedkar/4(87)/2024-25/ 136  
Comp. No. 37231416<sup>th</sup> May 2025**NOTICE INVITING QUOTATION**

Sealed quotations are invited from the reputed Contractor/Ship repairer/ Shipbuilder for "Repairing/Rectification of HPT BR Ambedkar's Port side HRP Unit" at NW-2 as per **Annexure - BOQ** & as per terms and conditions laid down below. The NIQ can also be downloaded from IWAI's website ([www.iwai.nic.in](http://www.iwai.nic.in)).

- (2) The work may be done as per following terms and conditions mentioned below:
- (i) The price may be quoted in both words and figures.
  - (ii) The price may be quoted including all the cost such as labour, transportation charges, all taxes excluding Good & Service Tax (GST) as applicable which will be paid on production of proof of payment. **No other charges shall be entertained.**
  - (iii) The repair work must be completed within 7 (Seven) days from the date of receipt of order at Neamati/ Bogibeel or anywhere in NW-2.
  - (iv) The firm has to submit documentary evidence of current copy of the Registration Certificate, PAN and GST.
  - (v) The payment shall be made by RTGS/ PFMS within 15 days from the date of receipt of bill after satisfactorily work done. The copy of RTGS details shall be submitted along with quotation.
  - (vi) In case of delay in completion of work liquidity damage @ 1.5 % per month to be computed on per day basis. The total amount of compensation for delay to be paid under this condition shall not exceed 10% of the value of work.
  - (vii) The firm shall be having experience working with IWAI / IWT Wing / Port, etc. Supporting documents has to be attach.
  - (viii) IWAI reserves the right to accept or cancel any / all quotations without assigning any reason or any prior notice.
- (3) The sealed quotation should reach this office latest by **20.05.2025 at 15:00 hrs** and will open on same day at **15.30 hrs**. No quotation will be accepted after the last date and time for submission of quotations.

Encl: as stated above.

  
DIRECTOR (I/c)

Copy to: Office Notice Board

**Annexure – BOQ**

**BOQ for Repairing/Rectification of HPT BR Ambedkar's Port side HRP Unit**

Sl no.	Description of Works	Unit	Qty.	Rate (in ₹)	Amount (in ₹)
i	Repair of Control Circuit of Port Side HRP to make it operational for its response/ operation with joy stick from wheel house and locally from the engine room as required as per direction of EIC.	Comp. Job	1		
Total amount (excluding GST)					

In Words: \_\_\_\_\_

\_\_\_\_\_

(GST extra as applicable)

AD(w)  
(VINAY KUMAR)  
16/05/2025